



[https://www.plexonline.com/30973b3d-de08-4a5c-b8b4-141ba52d4ee5/Plexus Control/Report Viewer 2.asp?URL=../ecr/ecr\\_print.asp&ECR Key=79...](https://www.plexonline.com/30973b3d-de08-4a5c-b8b4-141ba52d4ee5/Plexus%20Control/Report%20Viewer%202.asp?URL=../ecr/ecr_print.asp&ECR_Key=79...) 2/4

[https://www.plexonline.com/30973b3d-de08-4a5c-b8b4-141ba52d4ee5/Plexus Control/Report Viewer 2.asp?URL=../ecr/ecr\\_print.asp&ECR Key=79...](https://www.plexonline.com/30973b3d-de08-4a5c-b8b4-141ba52d4ee5/Plexus%20Control/Report%20Viewer%202.asp?URL=../ecr/ecr_print.asp&ECR_Key=79...) 3/4

151			RH			
D505-1057-153	On hold	505 - Wearplates - DART Replacement - Float - Heavy-Duty - LH or RH	Finished Good	D505-1057-153 D505-1057-153		IIN-D505-1057-RevB.pdf
D5633-1	On hold	CAP	Sub-assembly			

**INVENTORY DISPOSITION**

Part No Revision	Material No	Current Inventory Qty	Purchasing On-Order Qty	Qty Scheduled for Production
D505-1057-011		4 *	0 *	0 *
D505-1057-012		3 *	0 *	0 *
D505-1057-013		1 *	0 *	1 *
D505-1057-014		1 *	0 *	1 *
D505-1057-022		0 *	0 *	0 *
D505-1057-041		0 *	0 *	1 *
D505-1057-111		0 *	0 *	0 *
D505-1057-113		0 *	0 *	5 *
D505-1057-114		0 *	0 *	5 *
D505-1057-121		0 *	0 *	0 *
D505-1057-122		0 *	0 *	0 *
D505-1057-151		0 *	0 *	1 *
D505-1057-153		0 *	0 *	10 *
D5633-1		6 *	0 *	0 *

**EFFECTS**

Effect Group	Effects
1. Quarantine?	Immediate quarantine required
2. ECR Lead Assessment - Impacted Docs & Output	Drawing Change Required
3. ECR Lead Assessment - Status During ECR	UR - Full Under Review
4. Production Type	In-house production
5A. ECR Lead Assessment - MINOR Changes	Correction of drawing errors